



Notice to Mariners

Number: 22
Year: 2018
Issued: 30 April 2018
In force: **2009:**10, **2012:** 07, **2015:**04, **2016:**21 **2017:**02,24,
2018: 01,03,04,05,06,07,08,09,10,11,12,13,14,15,16,17,18, 20, 21,22

Roughs Shoal – approaches to Harwich Harbour

N W Roughs Tower Light Buoy damaged

Mariners are advised that the N.W. Roughs Tower Buoy [West Cardinal YBY VQ(9)] in position 51° 53.813' N 01° 28.771' E has been reported as damaged and leaning over.

An update regarding the condition of the buoy can be obtained from Harwich VTS on VHF Ch71

Captain M Dunn
Harbour Master