



Notice to Mariners

Number: 24
Year: 2020
Issued: 18th August 2020
In force: **2017:** 02, **2019:** 02,18,32, **2020:**04,09,12,22,23,24

Felixstowe Berth Fender Removal

Mariners are advised that work has commenced on the removal of fenders on Felixstowe Ro Ro 4 berth. Currently there are no fenders in place between bollard 20 (the double bollard) and bollard 22.

Work on removing the remaining fenders to the east (towards the existing Ro Ro 4 linkspan) will continue.

The Port of Felixstowe has specified that the berth between bollard 10 and bollard 22 is not to be used for vessels.

Captain M Dunn
Harbour Master and Marine Manager